

# Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



#### <u>WORK ORDER INFORMATION</u>

Work Order Name: WO/80008KN0811/1 Work Order Type: Weatherization

Audit Name: 80008KN0811-AUDIT

#### **CLIENT INFORMATION**

Client Name:

Address:

Client ID: 80008KN0811

Alt. Client ID: KNOX

#### <u>AGENCY INFORMATION</u>

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Mobile Home built in 1972

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0811 Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0811/1 Report Run On: 5/8/2010

**DOE Weatherization Assistant** Version 8.6.0

Page 1 of 8

## Measures

ı	Measure 1 Mol	bile Home Belly Repair	1000 sq f	t	Componen	ts			Inspected
С	•	belly with a durable prod s. Tape not allowed as a f l.		•				ıs	
					Estimated	Ī		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Mobile Home Belly Repair (+)	SqFt	1000					
2	Labor	labor	SqFt	1000					
C	ther Detail								
					State of the state				
								***************************************	
				Measur	e Sub Total:			Sub Total:	
	Fleld Notes:								

Comment •Remove old door before installing new door. A door is installed as a complete unit. A door is inclusive of weather-stripping, door lock, deadbolt, door stop, hinges, threshold, facing, strike plate, trim, jambs, paint(1st quality semi gloss color to be chosen by homeowner or sand/stained/seal), peep hole (at homeowner desire height), caulk, nailers. No changes allowed. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. All keys given to home owner not anyone else.										
						Estimated	<u>'</u>		Actual	
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Doors		Replacement doors	Each	1					
2	Labor		Replacement doors	Each	1					Merry
	Other Detail				Measur	e Sub Total:	. AAAANATTI		Sub Total:	and a second sec
	Field Note	es:				L				

Measure 2 Replace Doors Mandatory

Components D-3

Inspected

Alt. Client ID: KNOX

Measure 3 DWH Pi	pe Insulation			Component	ls			Inspected
Comment								
				Estimated			Actual	
# Material / Labor De	scription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation DV	VH Pipe Insulation	Each	1					
cor pro App for Ma	eludes labor cost. All rners must be cut operly. Refer to pendix A- Standards Weatherization aterials and Southeast old Guide.							
2 Labor DV	VH Pipe Insulation	Each	1					
Other Detail								
							A Committee of the Comm	
							de proposition de la constant de la	.//
			Measur	e Sub Total:		S	Sub Total:	
Field Notes:				nar				

Measure 4 DW	H Tank Insulation			Componen	ts		I	nspected
Comment extend	pressure relief pipe as nee	eded						
				Estimated	į		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Tank Insulation	Each	1					
	Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DWH Tank Insulation	Each	1					
Other Detail								
			Measu	e Sub Total:		borrer removes monacon or	Sub Total:	
Field Notes:								

Report Run On: 5/8/2010

	Measure 5 Rep	lace Heating [Electric]			Componen	ts			Inspected
C	Must pe Amana Housing 2.5 ton. thermos Thermos	s labor cost. Must be ins rform an ACCA Manual or or Goodman 13 Seer Sp Director for approval), 1 Final size will be determ tat. Must be equal to Ho stat (must submit equiva client on operation of th	J and subn lit Heat Pu 0 KW emo nined by th neywell's F lent to Hou	nit with mp (m ergend e ACC PRO 4	n invoice. Mu nust submit e by heat. Size CA Manual J. 000 Program	st be equ quivalent is approx Install ımable	ial to to imately	′	
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipmen	Replacement elec furnace (not used)	Each	1					The state of the s
2	Labor	Replacement elec furnace (not used)	Each	1	11110.4				
(	Other Detail								
			ı	Measur	e Sub Total:			Sub Total:	
THE PROPERTY OF THE PARTY OF TH	Field Notes:								

Client ID: 80008KN0811 Alt. Client ID: KNOX Work Order Name: WO/80008KN0811/1 Report Run On: 5/8/2010

Page 6 of 8

1	Measure 6 Fix I	mproper Venting (Clothe	es Dryer	)	Component	ts			Inspected
С	protrudir is 15 fee	ents installed with damper ng through pipe. Must be v t. No changes allowed. F ization Materials and Sou	vented to Refer to A	outsid Attachn	le of home. Nent A-Stand	/laximum			
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:		5	Sub Total:	
	Field Notes:								

Client ID: 80008KN0811 Alt. Client ID: KNOX Work Order Name: WO/80008KN0811/1 Report Run On: 5/8/2010

Version 8.6.0 Page 7 of 8

	Measure 7 Vapo	or Barrier Needed		1	Componen	ts			Inspected
C	walls and earth. M	6 mil poly. Must be insta d support piers. Must be ust be secured at all sea ization Materials and So	securely ms. Refer	fastene r to Atta	ed. Must be schment A-S	cleated o	down to		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	1539	127				
2	Labor	Labor	SqFt	1539		****			
(	Other Detail								
_				Measure	Sub Total:		]	Sub Total:	
	Field Notes:								
			Work Oi	rder Grai	nd Total:		Grand	d Total:	

Client ID: 80008KN0811 Alt. Client ID: KNOX Work Order Name: WO/80008KN0811/1 Report Run On: 5/8/2010

Version 8.6.0 Page 8 of 8